# Oil Field Environmental Incident Summary

Incident: 20140722012415 **Date/Time of Notice:** 07/22/2014 01:24 Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP BURLINGTON RESOURCES OIL & GAS COMPANY LP Well Name: CCU FOUR ACES CTB Field Name: CORRAL CREEK Well File #: Date Incident: 7/21/2014 Time Incident: 06:30 Facility ID Number: 416647-07 **WILLIAMS** Sec: 21 Qtr: SESW County: **Twp:** 147 **Rna**: 95 Location Description: Adjacent to the south east corner of the well pad Submitted By: Lewis Schoenberger Received By:

Contact Person: Lewis Schoenberger PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Pasture Affected Medium: Topsoil

1 Mile Distance Nearest Occupied Building: Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

> Spilled Units Recovered Units Followup **Units**

Gallons Oil 2

**Brine** Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 8/3/2016 Clean Up Concluded: 8/12/2014

Risk Evaluation:

None

Areal Extent:

#### Potential Environmental Impacts:

None

# Action Taken or Planned:

the oil impacted vegetation will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

## **Updates**

Date: 7/27/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to unspecified cause, sprayed off location. Follow-up is necessary.

Date: 8/6/2014 Status: Inspection Author: Martin, Russell

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

8/6/2014 at 12:58, on location. Met with personnel on site who witnessed event. Spray came out of flare and went directly south by southeast. Impact of spray difficult to detect on vegetation; however, a white pipeline marker shows clear impact. Marker is directly south by southeast of flare. Vegetation next to wellpad shows no clear visible impact. Electrical power box and wellpad fence line downhill to southeast show no visible staining. According to personnel, wind was very light at time of incident. Spray does not appear to have blown past the facility fence line.